

Ignition coil SKCO-0070125

UMFANGREICHES LIEFERPROGRAMM MIT ÜBER 10.000 VERSCHIEDENEN
REFERENZE

 Image not found or type unknown

UMFANGREICHES LIEFERPROGRAMM MIT ÜBER 10.000 VERSCHIEDENEN
REFERENZE

 Image not found or type unknown



OEM Reference

HUIZHONG	NEC90013A
ROVER	GCL219
ROVER	NEC000130
ROVER	NEC100870
SICCA	8530290

OEM Cross Reference

BorgWarner (BERU)	0040100502
MEAT & DORIA	10535
HITACHI	133838
HITACHI	133838
HITACHI	133838
EFI AUTOMOTIVE	155172
BREMI	20194
WE PARTS	220830283
NGK	48100
HELLA	5DA193175371
HELLA	5DA193175371
HELLA	5DA749475571
HELLA	5DA749475571
BEHR HELLA SERVICE	5DA749475571
HOFFER	8010535
SIDAT	8530290
FISPA	8530290
ERA	880226
TESLA	CL708
MOBILETRON	CR02
LUCAS ELECTRICAL	DMB947
DELPHI	GN1036412B1
DELPHI	GN1036412B1
JANMOR	JM5086
MOBILETRON	RGR02
NTK (NGK-GROUP)	U4002
NGK	U4002
BorgWarner (BERU)	ZS502